## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,291,133 B1

Page 1 of 1

APPLICATION NO.: 09/092546

DATED

: November 6, 2007

INVENTOR(S)

: Beat Kindler et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## **SPECIFICATION**

Column 3	Line 62	PTO "secured 21 on a rack"	Should Read secured on a rack
6	28	"snapped 16 together"	snapped together
7	57	"Lip 35,"	Lip 35
CLAIMS			
Column 12	Line 10	PTO "connector casing housing connecting section"	Should Read housing connecting section

Signed and Sealed this

Eighth Day of July, 2008

JON W. DUDAS Director of the United States Patent and Trademark Office